OUT63663

25X1

6X1 S E C R E T 222215Z CITE 2319

1967 NOV 22 22 28 Z

- 1. CAMERA B-24 WAS EMPLOYED ON MISSION G-995 FLOWN ON 21 NOVEMBER 1967. THE ORIGINAL NEGATIVE WAS PROCESSED BY NRTS.
 - 2. ORIGINAL NEGATIVE:
- A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

 B. 9R SIDE: INBOARD AND OUTBOARD EDGE FOG IS SLIGHT BUT
 PRESENT THROUGHOUT THE MISSION. INBOARD EDGE STATIC IS SLIGHT
 BUT PRESENT FROM HEAD TO TAIL OF THE MISSION. A ROW OF MINUS
 DENSITY DOTS SPACED 2.34 INCHES APART IS LOCATED 2.9 INCHES
 FROM THE INBOARD EDGE OF THE FILM FOR THE FIRST 37 FRAMES.
 A SECOND ROW OF MINUS DENSITY DOTS SPACED 2.34 INCHES APART
 IS LOCATED 4.06 INCHES FROM THE INBOARD EDGE OF THE FILM FOR
 THE FIRST 52 FRAMES OF THE MISSION. A HEAT SPLICE IS PRESENT
 BETWEEN FRAMES 642-643.
- C. 9L SIDE: THE METERING IS ERRATIC AND VARIES BETWEEN 0.35 TO 1.0 INCHES THROUGHOUT THE MISSION. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 12 WITH ASSOCIATED HANDLING MARKS. PINHOLE AND SMALL GOUGES WERE NOTED INTERMITTENTLY THROUGHOUT THE MISSION. INBOARD AND OUTBOARD EDGE STATIC WAS PRESENT THROUGHOUT THE MISSION. A HEAT SPLICE IS PRESENT IN FRAME 657.
- D. BOTH SIDES: THE LAST TITLED FRAME WAS 1309. THE DATA CHAMBER COUNTER RECORDED FRAME 1307 TWICE. THE SECOND FRAME 1307 WAS BLANK, AN ANOMALY PRESUMED DUE TO CAMERA SHUT DOWN AFTER TITLED FRAME 1309. MODE 5 WAS EMPLOYED THROUGHOUT THE MISSION.
 - 3. POSITIVES:
 - A. THE PI SUITABILITY IS GOOD.
 - B. PRINTING AND PROCESSING WERE GOOD.
- C. CLOUDS DEGRADE OR OBSCURE APPROXIMATELY 20 PERCENT OF THIS MISSION.
 SECRET

END OF MESSAGE

200 Selling Se

NGA review(s) completed.

